HABS TEX 130-COMF

PHOTOGRAPHS
WRITER: ISPORIGAL AND DESCRIPTIVE DATA
District of Texas+3

Wistoric American Baildings Survey
Bartlett Cocke, District Officer
615 Laverick Smilling, Sen ensonio, Texas.

HABS TEX 130- COMF

FALTIN HOUSE Comfort, Kendall County, Texas.

Owner: Waltin Estate

Date of Erection: 1854

Architect: Un nown

Builder: Mr. T. Toldbeck

Present Condition: It is in poor condition and is now used as a

storage house. The adobe bricks are exposed,

nearly all plaster having fallen away.

Number of Stories: One

Materials of Construction: Rock foundation; half timber and lime-

stone walls, cypress shingles roof and

cypress flooring.

Other Existing Records: None

Additional Data:

This house is constructed of part limestone and half timber and part adobe brick. The Southeast portion is of abode brick, which is covered with vertical siding with battens. The construction of rock and heavy cypress timbers is clearly shown as the plaster has fallen away. The timbers all have wire and square nails on them, which might be termed the beginning of our modern metal lath.

The house itself has four rooms. The opening at the North end was formerly a fireplace. A well canopy was added about 1880; its present condition is bad.

There was formerly a store building on the corner next to this house, and built at the sums time, but it has been replaced by a more modern building.

This information was secured from Mr. A. Brinkman, Historian of Comfort, Texas.

Author.

Charles Bertrand

APPROVED: Rammer Carles

Bartlett Cooke, District Officer.

3/12/34 11/1

mato: Movember 24, 1936